## Oil Field Environmental Incident Summary

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC
Well Operator: HESS BAKKEN INVESTMENTS II, LLC
Well Name: FRYBURG HEATH-MADISON UNIT F-814

Field Name: FRYBURG Well File #: 4325

Date Incident:10/10/2016Time Incident:13:00Facility ID Number:County:BILLINGSTwp:139Rng:101Sec:3Qtr:

Location Description: The location of the release was south of the location at 46.879016 -

130.405406. Production line ROW, USFS has been notified (via. verbal

notification)

Submitted By: Alberto Yates Received By:

Contact Person: Troy Brunsell

1501 MCKINNEY HOUSTON, TX 77010

General Land Use: Other - Described Above Affected Medium: Topsoil

**Distance Nearest Occupied Building:** 5.7 Mile **Distance Nearest Water Well:** 5.7 Mile

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

**Brine** 

Other 2 Gallons 2 gallons

Description of Other Released Contaminant:

Fresh Water with possible Hydro Carbon impacts.

Inspected: Written Report Received: 1/13/2017 Clean Up Concluded: 12/31/2016

Risk Evaluation:

There is no immediate risk to report at this time.

Areal Extent:

2'x2' area to the South of the FHMU F814 Location

## Potential Environmental Impacts:

No potential environmental impacts to report at this time

## Action Taken or Planned:

Release point has been Hydro vacuumed and exposed . Additional inspections will be ongoing to determine the failure point.

Wastes Disposal Location: All of the recovered wastes will be taken to an approved disposal

facility.

Agencies Involved: USFS (via. verbal notification)

## **Updates**

Date: 10/20/2016 Status: Reviewed - Follow-up Required Author: Crowdus, Kory

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release impacted areas off location. Follow-up is required.